Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division



Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division





Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division



Assistant Engineer

Assistant Executive Engineer
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-26

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division


Google
Bengaluru, Karnataka, India
94, 2nd B Cross Rd, Bhadrappa Layout, BDS Layout, Sri Balaji Krupa Layout, RK Hegde Nagar, Bengaluru, Karnataka 560077, India
Lat 13.066129°
Long 77.62857°
17/12/21 11:23 AM GMT +05:30
GPS Map Camera



Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division

Assistant Engineer

Assistant Executive Engineer

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division


Google
Bengaluru, Karnataka, India
71, 3rd Main Rd, Amam Enclave Layout, Ashwath Nagar, HBR Layout, Bengaluru, Karnataka 560045, India
Lat 13.048523°
Long 77.635814°
04/02/22 02:22 PM GMT +05:30
GPS Map Camera

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division

GPS Map Camera
Bengaluru, Karnataka, India
2JXG+47G, Fathima Layout, Bharath Nagar, Manayata Tech Park, Thanisandra, Bengaluru, Karnataka 560045, India
Lat 13.047662°
Long 77.625716°
25/01/22 01:44 PM GMT +05:30
Google

Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division

ಸಹಾಯಕ ಅಭಿಯಂತರರು
Assistant Engineer ಉಪ ವಿಭಾಗ

Assistant Executive Engineer
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪ, ಬಂಗಳೂರು-26

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division



Assistant Engineer

Assistant Executive Engineer

ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-26

Scanned by CamScanner

Name of Work: Maintenance of Water Supply Existing Borewells at Dasarahalli and Rachenahalli Surrounding area in ward no. 06 Byatarayanapura Sub Division



Assistant Engineer

Assistant Executive Engineer

Scanned by CamScanner

D

Maintenance of water supply existing Borewells at dasarahalli Rachenahalli Surrounding area in ward no.6 Byatarayanapura Sub-division.



ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-28

Scanned by CamScanner

Maintenance of water supply existing borewells at dasarahalli, Rathnahalli, Surrounding area, in ward no. 6, Byatarayanapura Sub-division.





ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-24

Scanned by CamScanner

Maintenance of water Supply existing Borewells at dasarahalli, Rachenahalli Surrounding area in ward no. 6 Byatarayanapura, Sub-division.

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬಿ.ಬಿ.ಎಂ.ಪಿ ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ

ಸಹಾಯಕ ಕಾರ್ಯನಿರ್ವಾಹಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ, ಬೆಂಗಳೂರು-26.

Scanned by CamScanner